


140 R



1. 1980

Reservdelar

Spare parts


Ersatzteile

Pièces de rechange


Varaosat

A


* compl 502 05 10-01




**B**

* compl 502 05 55-01


**F**

* compl 502 06 40-01






E * compl 502 05 75-01




K * compl 502 05 37-01


* compl 502 05 40-01



H




J



* compl 502 04 01-02



* compl 502 06 31-01




**Tillbehör
Accessories**

**Zubehöre
Accessoires**

Tarvikkeet




502 04 13-02 8" Maxi 200
502 04 58-01 8" Maxi 200, Maraton
502 04 69-01 8" Grass



501 58 02-01
501 07 21-01
502 01 71-01


501 31 77-01



502 50 76-01




502 06 01-01



502 04 70-01



502 02 00-01 = Compl.



502 02 01-01

502 02 06-01


502 02 30-02

502 02 31-01

502 02 29-02

502 02 27-01

★ 502 04 70-01



502 04 71-01 (M10)
502 04 71-02 (M12)

502 04 72-01

502 04 73-01
502 04 77-01 (50ft)
502 04 83-01 (250ft)

502 04 74-01

502 04 75-01

502 04 76-01

Beställn.-nummer Part number Best. Nr No de commande Varaos n:ro	Ruta Box Viereck Carreau Index	Anm. Remarks Anm. Notes Huom	Beställn.-nummer Part number Best. Nr No de commande Varaos n:ro	Ruta Box Viereck Carreau Index	Anm. Remarks Anm. Notes Huom	Beställn.-nummer Part number Best. Nr No de commande Varaos n:ro	Ruta Box Viereck Carreau Index	Anm. Remarks Anm. Notes Huom
20 24 292-42	H		50 14 508-01	C	★	50 20 505-01	H	
20 24 293-59	J, L		50 14 509-62	C		50 20 507-01	H	★
20 24 299-42	J		50 14 516-01	C, F		50 20 510-01	A	
20 24 325-55	K, L		50 14 524-01	C		50 20 511-60	A	
20 24 327-45	D, M		50 14 563-01	C	★	50 20 512-01	A	
20 24 329-12	K		50 14 566-01	A	★	50 20 513-01	A	
20 24 329-55	G, M		50 14 604-01	K		50 20 514-01	A	
20 24 330-55	J		50 14 605-01	K		50 20 515-01	A	
20 24 332-55	C		50 14 607-02	K		50 20 516-01	A	
20 24 333-59	M		50 14 609-01	K		50 20 519-01	A	
20 24 335-55	G, H, M		50 14 644-01	D	★	50 20 520-01	A	
20 24 341-55	L		50 14 657-01	J		50 20 521-01	A	
20 24 343-55	H		50 14 780-03	A		50 20 524-01	A	
20 24 344-55	A		50 14 854-01	J		50 20 525-01	A	
20 24 345-55	D		50 14 855-01	J		50 20 526-01	M	
20 24 368-42	M		50 14 856-01	J		50 20 528-01	M	
20 62 219-11	A, J		50 14 892-01	J		50 20 529-01	M	
20 62 364-11	M		50 15 162-03	J		50 20 530-02	G	
22 31 445-46	G		50 15 183-01	H		50 20 535-02	J	
22 36 360-46	M		50 15 415-01	J		50 20 537-01	K	
23 04 212-01	C		50 15 514-01	K		50 20 538-01	K	
23 06 190-12	J		50 16 032-03	C		50 20 540-01	K	
25 08 314-11	M		50 16 032-04	C		50 20 542-01	J	
25 08 318-12	J		50 16 032-05	C		50 20 544-02	H	
25 81 171-12	L		50 16 034-01	C		50 20 545-01	D	
28 16 137-01	J		50 16 329-02	J		50 20 552-01	A	
28 16 191-01	K		50 17 125-01	E		50 20 553-01	A	
28 20 015-01	L		50 17 126-01	E		50 20 554-02	H	
28 26 457-01	H		50 17 127-01	E		50 20 555-01	B	
28 35 255-11	M		50 17 130-01	E		50 20 562-60	J	
28 45 170-01	D		50 17 131-01	E		50 20 563-01	J	
28 88 140-12	A		50 17 133-01	E		50 20 565-02	J	
28 88 160-01	J		50 17 138-01	E		50 20 574-01	M	
28 88 170-01	D, J, K, C H, L, M		50 17 139-01	E		50 20 575-01	A, E	
28 95 190-01	A		50 17 145-01	E		50 20 576-01	E	
29 00 550-01	F		50 20 059-01	M		50 20 578-01	E	
29 31 170-01	L		50 20 083-01	M		50 20 579-01	E	
29 31 190-01	L		50 20 088-01	L		50 20 580-01	E	
29 31 190-39	L		50 20 114-01	L	★	50 20 581-01	E	
29 31 195-01	F		50 20 246-01	H		50 20 582-01	E	
29 64 310-02	L		50 20 401-02	L		50 20 583-01	E	
29 65 259-16	H		50 20 402-01	L		50 20 584-01	E	
29 70 155-01	L		50 20 405-01	L	★	50 20 585-01	E	
29 70 375-05	H		50 20 406-02	L		50 20 586-01	E	
29 71 342-01	H		50 20 407-02	L		50 20 589-01	H	
29 90 190-01	J, G, M		50 20 408-03	L		50 20 596-01	J	
50 10 817-01	J		50 20 412-01	L		50 20 598-01	J	
50 12 166-02	B		50 20 413-02	J		50 20 599-01	K	
			50 20 415-01	M		50 20 606-01	D	
			50 20 419-01	M		50 20 608-01	A	
			50 20 419-02	M		50 20 609-01	A	
50 12 211-01	E		50 20 422-02	M		50 20 625-01	M	
50 12 217-01	E		50 20 424-01	G, M		50 20 626-01	M	
50 12 222-01	E		50 20 425-01	G		50 20 627-01	M	
50 12 223-01	E		50 20 427-01	G		50 20 628-01	M	
50 12 224-01	E		50 20 437-01	M		50 20 631-01	M	
50 12 229-02	E		50 20 438-01	M		50 20 634-01	B	
50 12 230-02	E		50 20 441-01	M		50 20 635-01	C	
50 12 697-02	M		50 20 443-01	M		50 20 636-01	K	
50 12 763-01	H		50 20 446-01	L		50 20 637-01	M	
50 12 859-01	H		50 20 453-01	M		50 20 640-01	F	
50 13 065-01	M		50 20 460-01	M		50 20 647-01	M	
50 13 114-01	M		50 20 464-01	L		50 20 650-01	M	
50 13 114-02	M		50 20 502-01	H	★	50 20 651-01	D	
50 14 034-02	G							

★ = 502 06 42-01
Packingssats
Set of gaskets
Dichtungssatz
Jeu de joints
Tiivistesrj